

X-TYPE

DATE 02/05

XT204-11

SERVICE

TECHNICAL BULLETIN

Front Shock Absorber – Remove/Install – Revised Procedure & SRO Time

MODEL 2002 MY-ON X-TYPE VIN C00001-ON

Issue:

This Technical Bulletin has been issued for information only, to inform dealers of a change in the workshop procedure to remove/install the front shock absorber. The previous workshop procedure lowers one side of the front subframe to enable the shock absorber to be removed. The revised method lowers the rear of the subframe.

Action:

To remove/install the front shock absorber according to the new workshop method, see Global Technical Reference GTR Workshop Manual, section 204-01.

Global Technical Reference (GTR) Workshop Manual Information:

Dealer access: https://hub.franchise.jaguar.com
Internet access: https://www.jaguartechinfo.com

Parts Information:

DESCRIPTION PART NUMBER QTY
N/A - - -

Warranty Information:

Description	SRO	Previous Time	Revised Time
Front shock absorber - Vehicle Set - Renew	60.30.01	2.5 hrs.	2.5 hrs.
Front shock absorber - Left-hand - Renew	60.30.04	1.6 hrs.	1.5 hrs.
Front shock absorber - Right-hand - Renew	60.30.05	1.7 hrs.	1.5 hrs.

NOTE: THE INFORMATION IN TECHNICAL BULLETINS IS INTENDED FOR USE BY TRAINED, PROFESSIONAL TECHNICIANS WITH THE KNOWLEDGE, TOOLS, AND EQUIPMENT TO DO THE JOB PROPERLY AND SAFELY. IT INFORMS THESE TECHNICIANS OF CONDITIONS THAT MAY OCCUR ON SOME VEHICLES, OR PROVIDES INFORMATION THAT COULD ASSIST IN PROPER VEHICLE SERVICE. THE PROCEDURES SHOULD NOT BE PERFORMED BY "DO-IT-YOURSELFERS." DO NOT ASSUME THAT A CONDITION DESCRIBED AFFECTS YOUR CAR. CONTACT A JAGUAR DEALER TO DETERMINE WHETHER THE BULLETIN APPLIES TO YOUR VEHICLE.

